

<ul style="list-style-type: none"> <li>• <b>GLASS —FRONT DOOR—REVISED REGULATOR TO IMPROVE RISE TIME AND CLOSING PERFORMANCE</b></li> <li>• <b>WINDOW—POWER—FRONT DOOR—REVISED REGULATOR TO IMPROVE RISE TIME AND CLOSING PERFORMANCE</b></li> </ul>	<b>Article No. 91-12-4</b>
--	--------------------------------

**MERCURY:** 1991 CAPRI

**ISSUE**

A more powerful and moisture resistant power window regulator is now available for service use.

**ACTION**

If service is required, refer to the following service procedure.

1. Ensure that the service action described in TSB 90-25-7 has been performed to preclude glass and weatherstrip alignment type concerns.
2. If the window continues to be slow to rise and does not close properly, install a new front door window regulator. Refer to the 1991 Capri Shop, Page 4-2-08, for service details.

**OTHER APPLICABLE ARTICLES:** 90-25-7

**WARRANTY STATUS:** Eligible Under Basic Warranty Coverage

<b>OPERATION</b>	<b>DESCRIPTION</b>	<b>TIME</b>
911204AT	Replace Window Regulator - Both Sides	1.4 Hr.
911204A	Replace Window Regulator - One Sides	0.8 Hr.

**DEALER CODING**

BASIC PART NO.  
7023208

**OASIS CODES:** 102000, 205000

CONDITION  
CODE  
53

<b>PART NUMBER</b>	<b>PART NAME</b>
FOJY-7623200-A	Front Door Window Regulator - RH
FOJY-7623201-A	Front Door Window Regulator - LH